

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number ST01057WI

This Certificate issued to **Vision Safe Corporation
46-217 Kahuhipa Street
Kaneohe, HI 96744**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations. (Certification basis is set forth in Type Certificate Data Sheet T00003NY)

Original Product Type Certificate Number: T00003NY

Make: Bombardier

Model: BD-700-1A10, BD-700-1A11

Description of Type Design Change: Installation of Emergency Vision Assurance System (EVAS) in accordance with the following: (1) Midcoast Master Data List 35-416G001, Revision "A", dated January 8, 2002, or (2) Vision Safe Corporation Master Drawing List 206, revision "B", dated January 22, 2003, and (3) Airplane Flight Manual Supplement 35-416M001, revision "Original", dated January 11, 2002, or (4) Vision Safe Airplane Flight Manual Supplement No. 1, revision "1", dated March 28, 2003. And later FAA approved revisions to (1), (2), (3), or (4).

Limitations and Conditions: This approval should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved modifications will not introduce any adverse effect on the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 20, 2001

Date reissued: March 25, 2002, December 21, 2012

Date of issuance: February 26, 2002

Date amended: January 30, 2003, May 6, 2003,
February 8, 2006

By direction of the Administrator



Manuel R. Lopez
(Signature)

Manager, Cabin Safety and Mechanical Systems
Branch
Los Angeles Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.